

BOARD OF DIRECTORS
INDIAN WELLS VALLEY WATER DISTRICT

PLANT AND EQUIPMENT COMMITTEE
REGULAR MEETING

REPORT

TUESDAY, JULY 3, 2018 – 2:00 PM

BOARD ROOM
500 W. RIDGECREST BLVD., RIDGECREST

Attendees: Chuck Griffin, Chuck Cordell, Jason Lillion, Don Zdeba, and Travis Reed.

1. Call to Order

The meeting was called to order at 2:08 pm.

2. Committee/Public Comments

None.

3. Acceptance of Contract Work: Well 18 Repair & Rehabilitation (Best Drilling and Pump).

Best Drilling & Pump has completed the Well 18 Repair and Rehabilitation work. The total Adjusted Contract Amount is \$218,600.00. There were three (3) change orders, for a total amount of \$202,080.00. The Change Orders can be attributed to the addition of work for repairs, as the original contract only specified pulling and videoing the well. The Committee recommended the Board accept the Contract Work in the amount of \$218,600.00.

4. Acceptance of Contract Work: Eric Onstott Construction

Eric Onstott Construction has completed the Trench Patch Replacement work. The original Contract Amount was \$243,034.00. There was one (1) change order, for a total amount of \$59,753.80. The Change Order can be attributed to the addition of work to patch additional locations. The Committee recommended the Board accept the Contract Work in the amount of \$302,787.80.

5. WSIP Update: Update

Well 34: Well 34 is online. Layne Christensen/GE is scheduled to remediate the lower bearing issue the week of the 16th. At that time they will also remediate the oil that is in the sounding tubes.

Well 35: With the new fiscal year Staff will begin working on this project.

6. AMI Pilot Project: Update

Staff selected two of the four proposals for the customer engagement portal and received a demonstration from both. After viewing each product for functionality and cost staff selected Water Smart.

7. Arsenic Treatment Facilities: Update

Both treatment plants are operational. The issue with the pH probe drift on the influent of Plant 1 has been temporarily addressed by replacement with another probe. The faulty probe will be sent to the supplier for assessment and possible replacement. With the probe drift, all the arsenic lab tests have still come back under the state mandated level.

8. Future Agenda Items

None.

9. Adjournment

The meeting was adjourned at 2:25 pm.